

*Table 3.2: Millipore Testing Results*

Sample Time	Source Number	Source Description	Treatment Description
5/25/2007 12:00	1	Casa 83	No Chlorine
	2	Casa 84	No Chlorine
	3	Casa 25	Chlorine (25 drops)
	4	Casa 4	Chlorine + Vinegar
5/25/2007 3:00	5	Casa	Chlorine (12 drops)
	6	Casa	Chlorine (26 drops)
	7	Casa	Chlorine
5/25/2007 4:10	8	Eastern Spring	N/A
	9	Eastern Spring	N/A
5/26/2007 10:00	10	Tabara Valve/Sahanoa Tank	N/A
	11	Source Sand Filter	N/A
	12	Spring before Source Tank	N/A
	13	West River (Sample 1)	N/A
	14	West River (Sample 2)	N/A
5/27/2007 1:00	15	Bottled Water	No Additional Treatment
	16	Bottled Water	No Additional Treatment
5/26/2007 13:00	17	East River (Sample 1)	N/A
	18	East River (Sample 2)	N/A
	19	Marquette Water Quality Center Verification	Chlorine (25 drops) + Filtration

Small Colony	Large Colony	Approx Count
X		50
X		30
X		30
	X	10
X		30
X		100
X		50
	X	50
	X	30
X		10
X		10
X		30
X		30
X		TNTC
-	-	-
-	-	-
	X	100
-	-	3
-	-	-